

## Lead testing remediation

We had five locations failed the retest. The action that we are taking with each location is listed below.

1. Davenport Elementary school water fountain next to OTC room by gym. Remove entire fountain and take out of service. Not needed.
2. Fernwood school C205 library sink replace faucet with new and retest.
3. Alder ave. school Kitchen / Tea kettle take out of service not in use.
4. Miller school Library office / sink faucet replace with a new faucet and retest.
5. Swift school Kitchen sink faucet not in use take out of service.
6. Swift school room 60 retest bubbler after maintenance repairs.